



Before the Weld--Fault Detection



Programming the WeldMeter--Set Limit 1 (L1) with a tolerance band equally divided around the nominal dimension of a good nut positioned correctly (D_2). Set L1 to be Normally Open so the relay closes to allow the weld to proceed when LVDT output, D , is within the limit window. Set the upper value of the error band low enough to detect a large or upside-down nut (D_1). Set the lower bound of the limit window to detect a small or missing nut (D_3).

After the Weld--"Setdown Monitor"



Programming the WeldMeter--Set Limit 2 (L2) with a tolerance band equally divided around the nominal dimension of an acceptable "setdown" value. Set L2 to be Normally Open so the relay closes to signal an acceptable weld.

Programming a "head retracted" signal--To eliminate the need for a switch to detect that the ram has fully retracted and is ready for the next weld, program a third limit, L3, with a single value and normally open. When the head is retracted, the L3 relay will close and allow the next weld to start.