

DCP 700 TAC TIP

Subject: *How to recover from a Battery Failure*

To recover from a Battery failure, please follow these steps in order:

1. **General Calibration Reset:** See page 8-9
* All current programs will be lost.
2. **Check Model Code:** See Appendix A
* Model number is located on the back right hand side of instrument.
3. **PV Calibration:** See page 8-1
4. **Reload Configuration data:** See page 5-1
5. **Enter Tuning Parameter:** See page 6-1
6. **Renter Program data:** See page 4-1