

TAC TIP

ELECTROMAX V+ CONTROLLERS

CPU CARD # 046375 MODIFICATION

Following is a procedure to modify the CPU card part # 046375 to enable the use of a 5 VDC EEPROM (part # 193768).

CAUTION: The CPU card can be damaged by Electrostatic Discharge. Therefore, it is very important that a properly worn wrist strap be used to protect the circuit board from damage.

1). Remove the following components from the CPU card: C11, C14, Q14, Q15, R53, and R54.

NOTE: If using Mother card part # 063919 no additional hardware changes are required. If using Mother card part # 046448 there are additional hardware changes that are required to that Mother card.

For procedures to modify the Mother card part # 046448, procedures to replace and initialize the EEPROM, or any additional questions please call the Honeywell TAC at 1-800-423-9883.