

DCP550 TAC Tip

UNSTABLE DISPLAY DURING PV CALIBRATION

Problem: When connecting calibration device to input, the DCP 550 display will not stabilize. The display on the calibrator may also become unstable.

Solution : Place .1uf -50 wVDC ceramic capacitors from each lead of the DCP550 input to AC safety ground.
(Radio Shack #272-135 or equivalent)

