

TAC TIP

ELECTROMAX V+ CONTROLLERS

MOTHER CARD PART # 046448 MODIFICATION

Following is a procedure to modify the Mother Card part # 046448 to enable the use of a 5 VDC EEPROM (part # 193768).

CAUTION: The Mother Card can be damaged by Electrostatic Discharge. Therefore, it is very important that a properly worn wrist strap be used to protect the circuit board from damage.

1). On the Mother Card remove Voltage Regulator VR5 and Filter Capacitor C20.

NOTE: If using CPU card part # 063918 no additional hardware changes are required. If using CPU card part # 046375 there are additional hardware changes that are required to that CPU card.

For procedures to modify the CPU card part # 046375, procedures to replace and initialize the EEPROM, or any additional questions please call the Honeywell TAC at 1-800-423-9883.