

SA2000 Application Note

Problem: Motor is chattering

Solution: Black EAD Motor (discontinued from use summer 2005)

Check for short between White, Red and Black to case.

Check coil resistance 120V is 200 ohms (Red to White Black to White)

Check coil resistance 240V is 500 ohms (Red to White Black to White)